

TO:	Any Doors & Gates Jaymee-Lee Pauley PO Box 132 LEPPINGTON 2179	Report No:	SR-JFM22-43
		Date:	7 February 2022
		Reference:	JFM22-43
		Order No:	

DESCRIPTION OF WORK PERFORMED

**RE: HARVEY NORMAN ABDON CL, B/GREEN – TILE WAREHOUSE DOOR
EMERGENCY CALLOUT AFTER HOURS**

- Unjam door and get back into guides
- Reset limits as bottom of door too badly damaged and not recommend full open
- Hammer and cut with grinder as required
- Use of jimmy bar to get into position

The above works have been carried out in accordance with relevant Australian Standards and Codes of Practice.

RECOMMENDATIONS

- Replace curtain of door with new
- Until replacement, limit door use

Technician Name: COREY BROWN

Technician Signature: 

Customer Name:

Customer Signature

THANK YOU FOR YOUR BUSINESS

PHOTOGRAPHS



Measurement to back of guide across door



Measurement to back of guide across door – start position



Width of guide – both same size

THANK YOU FOR YOUR BUSINESS



Door opening height – not quite to drum



Door opening height – measurement at floor



Damaged guides



Damaged guide



Severe damage to guide



Bottom of shutter door – severely bent. Picture also shows drum location in relation to door opening.



Damaged door



Damaged door



Slat door had been painted same colour as building



Slats severely damaged. They are pulling apart

THANK YOU FOR YOUR BUSINESS



SERVICE REPORT

18 Mirambeena Street
BELMONT NTH NSW 2280

PHONE: 0437 013 490
OFFICE/FAX: 02 4945 5753
EMAIL: accounts@coreelectricalnsw.com.au

THANK YOU FOR YOUR BUSINESS