

Frank Davenport Electrical

0418 224 379

Job No:

213410

Date:

18-Aug-21

CUSTOMER

Chatswood Toyota

Contact
Phone

Ross

Job Address

578 Pacific Hwy
Chatswood

Service Type

Breakdown - door not working

Work done

Found lower level panel lift out of guides
Disassembled door and removed damaged brackets
Repaired brackets and wheel assemblies
Reassembled door into tracks
Setup limits and tested door

Parts used

Comments

NOTE: There was a piece of bent metal pipe near door which appears to have been inserted into door in an attempt to open it. This has bent the top wheel brackets causing the door to leave the tracks and fall

Track Issue