INVOICE

C.S. Door Services

ABN/13818582601
8 Chelsea Garden Court Wattle Grove N.S.W 2173

Craig Stammers
0437 674 760
csdoorssrvices@hotmail.com

Bill To

All Doors N.S.W.
P.O. Box 1 Lurnea N.S.W. 2170

Invoice Num	646
Date	30 Jul 2024
Due Date	29 Aug 2024
Terms	30 days

Description	Quantity	Rate	Amount
15/07/24 25866 Autolift 18 Loftus st Sydney Attend site Found chain off and curtain damaged Secure in open position	1	$275.00	$275.00
15/07/24 25843 ADG 2 Browne pde Warwick Farm Replace damaged parts Refit panellift Tension springs Test operation	1	$250.00	$250.00
15/07/24 25856 Ables 1 Clerke pl Kurnell Unjam roller door Refix guide Test operation	1	$115.00	$115.00
15/07/24 25868 Ables 79 Regent st Redfern Unjam curtain Put back in guides Reset limits Test operation	1	$115.00	$115.00
15/07/24 25855 Autolift 138 Barcom Ave Darlinghurst Replace grifco power box Test operation	1	$115.00	$115.00
15/07/24 25836 Autolift 2 Darley st Manly Unjam curtain Put back in guides Retention roller Test operation	1	$115.00	$115.00
16/07/24 25872 ADG 27 Belmore st Burwood Put wheels back in tracks Tighten cables Test operation	1	$275.00	$275.00
16/07/24 25874 Stratawide 11 Hassall st Parramatta Attend site Found slats to damaged to operate Isolate and leave open	1	$275.00	$275.00
16/07/24 25859 Ables 5 Saggart Field rd Minto Realign curtain Refit chain Tighten motor sprocket Grease guides Test operation	1	$145.00	$145.00
16/07/24 25869 Autolift 2/231 Marshall rd Kirrawee Panelbeat slats Reset overload Test operation	1	$115.00	$115.00
16/07/24 25862 Autolift 20 Woniora rd Hurstville Rewire and tighten keyswitch Test operation	1	$115.00	$115.00
16/07/24 25713 Autolift 36 Bunyala st Blakehurst General service to carpark panellift General service to fire shutter Test operation	1	$100.00	$100.00

Description	Quantity	Rate	Amount
16/07/24 25681 Autolift 2 Cook st Sutherland General service to carpark shutter General service to fire shutter Test operation	1	$100.00	$100.00
16/07/24 25677 Netstrata 552 President ave Sutherland General service to carpark shutter Found motor leaking and broken springs Test operation	1	$100.00	$100.00
16/07/24 25682 Autolift 9 Moore st Sutherland General service to carpark shutter Test operation	1	$100.00	$100.00
17/07/24 25887 Ables 20 Spencer st Rose Bay Put back in guides Test operation through contactors Found no response from board	1	$115.00	$115.00
17/07/24 25882 All Doors 18 Railway st Banksia Measure for new motor	1	$50.00	$50.00
17/07/24 25712 Autolift 50 Pemberton st Botany General service to carpark shutter Test operation	1	$100.00	$100.00
17/07/24 25873 Autolift 50 Pemberton st Botany Found roller rubbing on off end bracket Realign roller Realign curtain Test operation	1	$115.00	$115.00
17/07/24 25861 IB Property 26 Kippax st Surry Hills Install aluminium panel Refit haspen staple Test operation	1	$115.00	$115.00
17/07/24 25772 Dominator 33 Wilga st Burwood Realign photo beam Reset limits Test operation Witness cars exiting on remote	1	$115.00	$115.00
17/07/24 25853 Ables 24 Roselands dr Roselands Attend site No access	1	$115.00	$115.00
18/07/24 25853 Ables 24 Roselands dr Roselands Replace faulty central motor Wire in new motor Set limits Test operation	1	$250.00	$250.00
18/07/24 25639 Independent 3 Lancaster st Ingleburn Attend site Found roller damaged beyond repair	1	$115.00	$115.00
18/07/24 25896 Autolift 31 Cumberland st Ingleburn Realign photo beam Test operation	1	$115.00	$115.00
18/07/24 25888 Elite 12 Bathurst st Liverpool Replace damaged torsion bar Replace cables Retention springs Test operation	1	$200.00	$200.00
18/07/24 All Doors 106 Euston rd Alexandria Realign and tighten photo beam Test operation	1	$275.00	$275.00
18/07/24 25902 Autolift 18 Drummoyne Ave Drummoyne Straighten photo beam bracket Lubricate panellift Test operation	1	$275.00	$275.00
19/07/24 25905 ADG 20 Lexington dr Bella Vista Attend site Found sprocket missing off motor Found track impacted	1	$115.00	$115.00

Description	Quantity	Rate	Amount
19/07/24 25908 Upstate 688 Pittwater rd Brookvale Attend site Found it to be glass sliding doors has an intermittent fault.	1	$115.00	$115.00
19/07/24 25880 Autolift 64 Penkivil st Bondi Replace motor Wire in motor Set motor Test operation	1	$200.00	$200.00
19/07/24 25832 Autolift Captain Cook dr Woolooware Bay Install 2 hand operated fire shutters Test operation	1	$330.00	$330.00

Thank you for your business.

Subtotal	$5,025.00
GST (10%)	$502.50
Total	$5,527.50
Paid	$0.00
Balance Due	**$5,527.50**

Payment instructions

Bank transfer

Bank Name: Commonwealth Bank
Beneficiary Name: Craig Stammers
Account Number: BSB 062424 ACCOUNT 10507113