Autolift Garage Doors & Gates
12 Larkin Street
Riverwood NSW 2210

Tel: 02 9534 0444

ABN 170 689 535 60

PURCHASE ORDER

All Doors NSW Pty Ltd

PO Box 132
Leppington NSW 2179

Order Date
7/7/2025

Order No
018720

Deliver To: 5 Haran Street
Mascot NSW 2020

Contact: Wayne Small
Job # Ref: 76818

Delivery Date Required -

Delivery Instructions
not urgent but must book in with either contact

Qty	Unit Type	Part No	Item	Unit Charge	Total
1	EA service call		The roller shutter does not automatically open upon detection of a fire within the basement carpark and it does not open in the event of a power failure. This could be due to a battery failure which is why the door contractor is required to further investigate and also confirm operation of the fire trip as the cable is connected to the motor. Door contractor will also have to check power failure as we believe there is a battery back up inside their control box. site contacts Martins 0468939414 & Xue 0430389408	$0.00	$0.00

Subtotal:	$0.00
Total GST:	$0.00
Total:	$0.00

Qty Total: 1

Notes