WWC - CROYDON PARK - 62678-002

Job #28456

Status: Completed

Client:
WHITE WOLF CONSTRUCTIONS
77 Portland Street
Croydon Park
2133
New South Wales

Date	Description	Quantity
2025/03/21 11:25	11.10-11.25 Attend site Found gate frame bent Impacted by car Gate still operational QUOTE TO FOLLOW	1.00
2025/04/04 08:45	Attend site Found gate frame bent Impacted by car Gate still operational Motor still in fair condition Only way to repair gate would be to probably replace	1.00

Attachment Report & Quote Request 62678-002.pdf

Description: PO

White Wolf Constructions Pty Ltd
ABN 23 137 769 183 ACN 137 769 183
NSW Lic: 219244C ACT Lic: 20161059
T: 1300 136 369
7 Wurrook Cct, Caringbah NSW 2229
admin@wwconstructions.com.au
www.whitewolfconstructions.com.au

REPORT & QUOTE REQUEST 62678-002

Trade Details

Raised	21/03/2025	**Insured Contact**	Mrs. NEETU GUPTA
Trade Name	All Doors NSW Pty Ltd	**Insured Address**	77 PORTLAND STREET CROYDON PARK NSW
Trade Phone	0417 975 669	**Insured Phone**	0432486312
Trade Email	sales@alldoorsnsw.com.au	**Alternate Phone**	
WWC Ref	62678	**WWC Contact**	Luke Walton - 1300 136 369/0438 432 397

Work Order Details

WWC Notes
Hi Team,
Please attend and carry out trade report on rear elevation roller gate.
Thank you.

Please attend site to complete a detailed causation report and quote to repair, ensuring you include the following in your report:
- A clear description of the cause of the damage and an indication of how long this has been occurring
- Please report back to WWC immediately if you identify any further reporting is required to determine the cause of damage, for example and leak detection report performed by a plumber or a specialist roof report
- Any maintenance related issues including the overall condition of the property
- Any design issues which may have contributed to the cause of the damage or ongoing damage
- A recommended scope to repair the damage
- A quote for repairs or replacements based on your report (as a separate document)
- Extensive photos clearly labelled, including a photo of the front of the property
- Details of any specialist reports you deem may be required to determine the cause of the damage
- Photos of safety equipment used if relevant

Report Details

Description	Total
Report & Quote Request	$200.00
Additional costs appoved.	$50.00

Total excludes GST	**$250.00**
GST	**$25.00**
Total including GST	**$275.00**

WHITE WOLF
CONSTRUCTIONS

POWERED BY WOLF | WORKING ON-LINE FACILITY

Subcontractor’s Responsibilities

- Contact the insured within 4 hours of allocation.
- Attend site within 2 days or any other timeframe agreed to or instructed by WWC.
- Submit Report and/or Quotation as required within 48hrs of site attendance.
- Familiarise itself with the attached Terms & Conditions.
- Immediately advise WWC of any suspected asbestos.
- Immediately advise WWC of any suspected mould.
- Ensure all waste is removed from site to an approved waste transfer station.
- Provide WWC with handover certificates and photos of competed scaffolds, perimeter roof rail safety systems.
- Provide WWC with photos of all PPE used during the course of the works.
- Provide adequate protection to existing flooring, furnishings & finishes to the satisfaction of WWC. Ensure place of work is left neat & tidy upon completion of each day or works.
- Whilst onsite please refrain from discussing any specifics relating to the Claim including dollar value. Any queries should be politely directed back to WWC to answer on 1300 136 369.
- Start and progress information must be forwarded/updated on a regular basis or as requested by WWC.

High Risk Construction Work identified in relation to this work order

☐ Risk of a person falling more than 2 metres
☐ Demolition of a load bearing element of a structure
☐ The likely disturbance of Asbestos
☐ Temporary propping to prevent collapse
☐ Works on or near pressurised gas main or piping
☐ Works on or near refrigerant lines
☐ Works on or near energised electrical services
☐ Works on or near a roadway involving the movement of vehicles
☐ Works near mobile plant equipment
☐ Works near water that involves a risk of drowning
☐ Works near Point of Attachment (POA)
☐ Ensure all work complies with current NSW and ACT legislation for Crystalline Silica, including obtaining necessary disposal or work permits?

Pursuant to WHS Regulation clause 299, the subcontractor is responsible for preparing a Safe Work Method Statement for the High Risk Construction Work identified above.

White Wolf Constructions may request to review any SWMS during a site inspection or safety audit.

Attachment photo.jpg

Description: gate bent



Attachment photo.jpg

Description: motor



Attachment photo.jpg

Description: gate



Attachment photo.jpg

Description: gate outside

