ESC Randwick

Job #28096

Status: Completed

Assigned to:
Rove Crawford
0474749049
ianrovercrawford@gmail.com

Client:
Auto Lift Garage Doors
Matt Volpatti
4 Dudley Street Randwick
2031
NSW

Stuck closed
Rene 0410 542 995

Summary

Description	Amount	Tax	Total
Time	620.00	62.00	682.00
		Subtotal	**682.00**
		Less: Payments	0.00
		Total	**682.00**

Labour

Date	Description	Hours	Rate	Tax	Amount
16-02-2025 12:33	11-25 - 12-45 Assess shutter broken springs and shaft broken on motor door crashed down in guides Cut curtain down middle and strip curtain to a height of 2300 to give clear access NEW SHUTTER WITH ATHENA - $9135+gst motor included	1.00	620.00	10.00%	620.00
				Subtotal	**620.00**
				Total Tax	62.00
				Total	**682.00**

Notes


Date	Description	Attachment
16-02-2025 12:45	photos	photo.jpg
16-02-2025 12:46	photos	photo.jpg

16-02-2025 12:46	photos	photo.jpg
16-02-2025 12:46	photos	photo.jpg
16-02-2025 12:47	photos	photo.jpg
16-02-2025 12:47	photos	photo.jpg
16-02-2025 12:47	photos	photo.jpg
16-02-2025 12:48	photos	photo.jpg
17-02-2025 07:11	Athena required	
17-02-2025 09:32	Assess shutter broken springs and shaft broken on motor door crashed down in guides Cut curtain down middle and strip curtain to a height of 2300 to give clear access All the residents committee were on site and they want other options for a new door or something else that can be suggested as the door height is only 2.25 up the top of the ramp and the door at the bottom of the ramp is 4 m high existing steelwork Thompsons 150 x 150 steel angle Between steel 5964 wide Door height 3800 Existing drum LH 12 b chain Curtain has sections of perf and plain lots of 10 perf 10 plain throughout the curtain Cut slat 5780 75 mm 11-25 - 12-45	
17-02-2025 11:37	2300H x 5780 C/S 75mm Perf Sections, Duralloy P/Coat - $ 3610.00 + GST 3800H x 5780 C/S 75mm Perf Sections, Duralloy P/Coat - $ 4760.00 + GST Motor by All Doors Mark Condron	
20-02-2025 16:10	motor	photo.jpg
20-02-2025 16:10	photos	photo.jpg
20-02-2025 16:10	photos	photo.jpg
20-02-2025 16:11	photos	photo.jpg
20-02-2025 16:11	photos	photo.jpg
20-02-2025 16:11	photos	photo.jpg
20-02-2025 16:18	the main address daintrey	

Attachment photo.jpg



Attachment photo.jpg



Attachment photo.jpg



Attachment photo.jpg



Attachment photo.jpg



Attachment photo.jpg




Attachment photo.jpg




Attachment photo.jpg




Attachment photo.jpg



Attachment photo.jpg




GfA - ELEKTROMATEN
Australia Pty Ltd
P.O Box 267
Roseville 2069 NSW
Telephone: 02 9882 2782
Facsimile: 02 9882 2783
Email: j.bourges@gfa-elektromaten.net
Web: www.gfa-elektromaten.de
ELEKTROMATEN
MADE IN GERMANY
TÜV
Baumuster geprüft
KE 17.24-25,40
ID 11048391-38
No. 10003692 00013
170 Nm
3N~ 400V 50 Hz
1,9 A
+40°C
IP 54
-5°C
S40
2012

Attachment photo.jpg



Attachment photo.jpg



Attachment photo.jpg

