SERVICE REPORT

Core Electrical
New South Wales
ABN: 50 230 436 026 LIC NO: 92919C

18 Mirambeena Street
BELMONT NTH NSW 2280
PHONE: *0437 013 490*
OFFICE/FAX: *02 4945 5753*
EMAIL: *accounts@coreelectricalnsw.com.au*

TO:	Any Doors & Gates Jaymee-Lee Pauley PO Box 132 LEPPINGTON 2179	**Report No:**	SR-AMJ23-120
		Date:	20 June 2023
		Reference:	AMJ23-120
		Order No:	

DESCRIPTION OF WORK PERFORMED

RE: HARVEY NORMAN BENNETTS GREEN

- Fault find dock 1; The Dock 1 labelled is a roller door on a drum – other doors are slats; so with extreme lifting forcing door up over drum; could only lift it to approximately 100 mm off ground
- Another dock sometimes also referred to as 1 (Dock 5) has a mechanical chain now; it was also determined that the other day others hadn't secured correctly; shut on top of rat bait station and not engaged chain
- Modified dock 1 door as catching alarm system; 1.2 metres above ground

The above works have been carried out in accordance with relevant Australian Standards and Codes of Practice.

RECOMMENDATIONS

- Ensure door locked down fully; operators
- If not happy replace curtain with heavier more expensive shutter slats like other doors

Technician Name:	**COREY BROWN**
Technician Signature:	
Customer Name:	
Customer Signature	

THANK YOU FOR YOUR BUSINESS

Core Electrical
New South Wales
ABN: 50 230 436 026 LIC NO: 92919C

SERVICE REPORT

18 Mirambeena Street
BELMONT NTH NSW 2280
PHONE: *0437 013 490*
OFFICE/FAX: *02 4945 5753*
EMAIL: *accounts@coreelectricalnsw.com.au*

PHOTOGRAPHS



Dock 5 - Rat bait station caught under door



Dock 1 – Roller door curtain



Dock 1 – Roller door curtain (excellent condition)




Dock 1 – Roller door curtain (excellent condition)

THANK YOU FOR YOUR BUSINESS

Core Electrical
New South Wales
ABN: 50 230 436 026 LIC NO: 92919C

SERVICE REPORT


18 Mirambeena Street
BELMONT NTH NSW 2280
PHONE: *0437 013 490*
OFFICE/FAX: *02 4945 5753*
EMAIL: *accounts@coreelectricalnsw.com.au*



Grifco mechanical with chain drive for door drum



Alarm that was being caught





Other doors facing road with slats attached to drums

THANK YOU FOR YOUR BUSINESS