SERVICE REPORT

Core Electrical
New South Wales
ABN: 50 230 436 026 LIC NO: 92919C

18 Mirambeena Street
BELMONT NTH NSW 2280
PHONE: *0437 013 490*
OFFICE/FAX: *02 4945 5753*
EMAIL: *accounts@coreelectricalnsw.com.au*

TO:	Any Doors & Gates PO Box 132 LEPPINGTON 2179	**Report No:**	SR-JFM24-220
		Date:	8 March 2024
		Reference:	JFM24-220
		Order No:	

DESCRIPTION OF WORK PERFORMED

RE: SERVICE CALL - DOMAYNE WEST GOSFORD

- Fault find system; found fusable link broken
- Attempted to re-attach but when running, plate slides and disconnects from magnet
- Clamped into place; fuse link may be required and reconnect wire cabling

The above works have been carried out in accordance with relevant Australian Standards and Codes of Practice.

RECOMMENDATIONS

- Re-position wire that attaches to magnet so it is straight; also install turn buckle to assist with tension
- Long term replace with battery backup; broken motors

Technician Name:	**COREY BROWN**
Technician Signature:	
Customer Name:	
Customer Signature	

THANK YOU FOR YOUR BUSINESS

Core Electrical
New South Wales
ABN: 50 230 436 026 LIC NO: 92919C

SERVICE REPORT

18 Mirambeena Street
BELMONT NTH NSW 2280
PHONE: *0437 013 490*
OFFICE/FAX: *02 4945 5753*
EMAIL: *accounts@coreelectricalnsw.com.au*

PHOTOGRAPHS






THANK YOU FOR YOUR BUSINESS


SERVICE REPORT

Core Electrical
New South Wales
ABN: 50 230 436 026 LIC NO: 92919C

18 Mirambeena Street
BELMONT NTH NSW 2280
PHONE: *0437 013 490*
OFFICE/FAX: *02 4945 5753*
EMAIL: *accounts@coreelectricalnsw.com.au*







THANK YOU FOR YOUR BUSINESS