JOHNS LYNG - MARSFIELD - APR031257P

Job #28369

Status: Completed

Client:
JOHNS LYNG
5 Fay Place
Marsfield
2122
New South Wales

Date	Description	Quantity
2025/03/17 11:30	11-20 - 11-35 Assess roller door b/d firma door with ata motor There is no physical damage to the door and the door and motor run smoothly. Yes the door is old but the door is totally fine and working in good condition.	1.00

Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos




Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: Between the carport post and the post holding the door is 410 mm

If door is to be replaced
Measurements
2850 cut
2200 high
Colour cottage green
ATA motor weather Drive



Attachment photo.jpg

Description: 1

