

MAINTENANCE INSPECTION REPORT # 15181
DATE: 14th October 2021
ADDRESS: 191-195 Bridge Rd Glebe
ARRIVAL TIME: 10:40am

**SERVICE INSPECTION CHECK LIST** Below is a check list of all items carried out during each visit. All items are checked for damage & fatigue

**ROLLER SHUTTERS**

ITEM	OK	REQUIRES ATTENTION, NOTE DETAIL
Check that track is secure	✓	
Check if track is worn & losing shape	✓	
Check integrity of door, that there is no fatigue, broken weld etc.	✓	
Check all stops or catches are secure and in correct position	✓	
Check posts are firmly secured	✓	
Check limits are set correctly	✓	
Check receiver and reception	✓	
Check motor casing for cracks & operation	✓	
Check PE Beam alignment and reflector	✓	
Check PE Beam is sealed properly from insects	✓	
Check chain tension	✓	
Check motor is adjusted correctly	✓	

**BOOM GATES**

Check operation of electronics		
Lubricate all moving parts		

TECHNICIAN (print name) Ian

SIGNATURE 