AUTO LIFT
GARAGE DOORS & GATES

12 Larkin St, Riverwood NSW 2210
Ph: 02 9534 0444

MAINTENANCE INSPECTION REPORT #	Panel lift
DATE:	11/8/25
ADDRESS:	6-8 Monash Rd Gladesville.
ARRIVAL TIME:	

SERVICE INSPECTION CHECK LIST Below is a check list of all items carried out during each visit. All items are checked for damage & fatigue

ROLLER SHUTTERS

ITEM	OK	REQUIRES ATTENTION, NOTE DETAIL
Check that track is secure	✓	
Check if track is worn & losing shape	✓	
Check integrity of door, that there is no fatigue, broken weld etc.	✓	
Check all stops or catches are secure and in correct position	✓	
Check posts are firmly secured	✓	
Check limits are set correctly	✓	
Check receiver and reception		N/A
Check motor casing for cracks & operation	✓	
Check PE Beam alignment and reflector	✓	
Check PE Beam is sealed properly from insects	✓	
Check chain tension	✓	
Check motor is adjusted correctly	✓	

BOOM GATES

Check operation of electronics		
Lubricate all moving parts		

TECHNICIAN (print name) Craig Stammers

SIGNATURE _____