

<b>TO:</b>	Any Doors & Gates Jaymee-Lee Pauley PO Box 132 LEPPINGTON 2179	<b>Report No:</b>	SR-JAS21-34
		<b>Date:</b>	7 July 2021
		<b>Reference:</b>	JAS21-34
		<b>Order No:</b>	

### DESCRIPTION OF WORK PERFORMED

**RE: HARVEY NORMAN BENNETTS GREEN – 11 STATHAM STREET, DOCK 5  
JOB #14365 – ADG 17905**

- Fault find door
- Cut and removed Nylofelt; jamming door up
- Lubricated guides
- Obtain details for replacement
- Check spring tension – broken spring inside drum

The above works have been carried out in accordance with relevant Australian Standards and Codes of Practice.

### RECOMMENDATIONS

- Replace immediately as next time door will most likely need to be screwed shut and placed Out of Service; door is at end of life – not economical to repair

**Technician Name:** COREY BROWN

**Technician Signature:** 

**Customer Name:**

**Customer Signature**

**THANK YOU FOR YOUR BUSINESS**

**PHOTOGRAPHS**



*Eastern Guide*



*Western Guide*

**THANK YOU FOR YOUR BUSINESS**




*Accessories attached to door i.e. alarm system*



*Nylofelt pulling off eastern side*



*Nylofelt pulling off western side;  
motor is attached to this side*




*Door*




*Extensive corrosion to curtain*



*Door opening eastern side*



*Door opening eastern side*



*Door opening western side*



*Door opening western side*



*Measurement from back of guides*



*Measurement to back of*



*Measurement back of guides*




*Measurement back of guides*



*Door opening*

**THANK YOU FOR YOUR BUSINESS**




*Nylofelt rusting off*



*Nylofelt rusting off*

**THANK YOU FOR YOUR BUSINESS**



*Removed Nylofelt jamming up,  
condition of door is bad and  
replacement is not feasible*

**THANK YOU FOR YOUR BUSINESS**