**Able Door Services (NSW) Pty Ltd**
ABN 90 097 064 527
507-509 Victoria Street
Wetherill Park NSW 2164

Tel. 02 9757 1877
Fax. 02 9757 1652
www.abledoors.com.au
doorservice@abledoors.com.au

# CUSTOMER JOB NO. 26653

## Site Details

| | |
|---|---|
| **Name** | 2 BOBBIN HEAD ROAD |
| **Address** | 2 BOBBIN HEAD ROAD<br>PYMBLE NSW 2073 |
| **Contact** | ROBERT |
| **Telephone** | 0412 487 761 |
| **Mobile** | |
| **Email** | |

## Customer Details

| | |
|---|---|
| **Name** | 91122: 2 BOBBIN HEAD ROAD, PYMBLE, 2073, NSW |
| **Address** | C/- JAMESONS & ASSOCIATES UNIT SERVICES PTY LTD TRADING AS STRATA MANAGEMENT<br>PO BOX 2001<br>SPIT JUNCTION NSW 2088 |
| **Contact** | |
| **Telephone** | 02 8969 3338 |
| **Mobile** | |
| **Email** | joannes@jamesons.com.au |

## Work Requested

**DOOR SERVICE REQUEST**
**JOB TAKEN: 17/08/2023**
**JOB COMPLETED: 18/08/2023 (AD)**

PANEL LIFT CLOSING OUT OF ALIGNMENT

CABLE ON ONE SIDE NOT WRAPPING AROUND THE TORSION BAR CORRECTLY

CONFIRMED WITH ROBERT FOR ATTENDANCE AROUND LUNCH TIME - TECH TO RING ON THE WAY

## Schedule

| Date Schedule | Date Performed | Scheduled Start | Scheduled Finish | Actual Start | Actual Finish | Total |
|---|---|---|---|---|---|---|
| | | | | | | |
| | | | | | | |
| | | | | | | |

## Work to be Performed

| Description | Required |
|---|---|
| | |
| | |
| | |

## Work Completed Notes

## Materials Used

| Description | Location | Used |
|---|---|---|
| | | |
| | | |
| | | |

**The above works have been supplied and installed to my complete satisfaction.**

**Customer:**

Print Name _____ Signature _____

**The above works have been supplied and installed as per relevant Australian Standards.**

**Technician:**

Print Name _____ Signature _____