**Able Door Services (NSW) Pty Ltd**
ABN 90 097 064 527
507-509 Victoria Street
Wetherill Park NSW 2164

Tel. 02 9757 1877
Fax. 02 9757 1652
www.abledoors.com.au
doorservice@abledoors.com.au

# CUSTOMER JOB NO. 31702

| Site Details | |
|---|---|
| **Name** | 66 Clarence St |
| **Address** | 66 Clarence St<br>Sydney NSW 2000 |
| **Contact** | Grant |
| **Telephone** | 0417 924 505 |
| **Mobile** | |
| **Email** | |

| Customer Details | |
|---|---|
| **Name** | KNIGHT FRANK SYDNEY METRO |
| **Address** | GPO BOX 187<br>SYDNEY NSW 2000 |
| **Contact** | GRANT BRUMFIELD |
| **Telephone** | 0466516903 |
| **Mobile** | |
| **Email** | |

## Work Requested

SAME DAY SERVICE

JOB TAKEN 11/03/2024

COMPLETE 11/03/2024

SHUTTER SLATS HIT AND DAMAGED

GET TEMP OPERATION AND QUOTE REPLACEMENT SLATS

## Schedule

| Date Schedule | Date Performed | Scheduled Start | Scheduled Finish | Actual Start | Actual Finish | Total |
|---|---|---|---|---|---|---|
| | | | | | | |
| | | | | | | |
| | | | | | | |

## Work to be Performed

| Description | Required |
|---|---|
| | |
| | |
| | |

## Work Completed Notes

## Materials Used

| Description | Location | Used |
|---|---|---|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

**The above works have been supplied and installed to my complete satisfaction.**

**Customer:**

Print Name _____ Signature _____

**The above works have been supplied and installed as per relevant Australian Standards.**

**Technician:**

Print Name _____ Signature _____