**Able Door Services (NSW) Pty Ltd**
ABN 90 097 064 527
507-509 Victoria Street
Wetherill Park NSW 2164

Tel. 02 9757 1877
Fax. 02 9757 1652
www.abledoors.com.au
doorservice@abledoors.com.au

# CUSTOMER JOB NO. 43831

## Site Details

| | |
|---|---|
| **Name** | 2-8 SUSAN PARADE |
| **Address** | 2-8 SUSAN PARADE<br>CASTLE HILL NSW 2154 |
| **Contact** | |
| **Telephone** | |
| **Mobile** | |
| **Email** | |

## Customer Details

| | |
|---|---|
| **Name** | 83832: 2-8 SUSAN PARADE, CASTLE HILL, 2154, NSW C/- O'CONNORS STRATA |
| **Address** | UNIT 1/24 ROSS STREET<br>PARRAMATTA NSW 2150 |
| **Contact** | |
| **Telephone** | 02 9683 1811 |
| **Mobile** | |
| **Email** | UPLOAD_TO@SMATA |

## Work Requested

**DOOR SERVICE REQUEST**
**JOB # 43831**

**JOB COMPLETE -**
**TECH - A/DOORS**

**BASEMENT - ENTRY SECTIONAL PANEL LIFT**

SITE HAS REPORTED ENTRY DOOR INOPERABLE - SEE PHOTOS
INSPECT & REPAIR IF POSSIBLE

QUOTE ANY FURTHER WORKS/PARTS IF REQUIRED

## Schedule

| Date Schedule | Date Performed | Scheduled Start | Scheduled Finish | Actual Start | Actual Finish | Total |
|---|---|---|---|---|---|---|
| | | | | | | |
| | | | | | | |
| | | | | | | |

## Work to be Performed

| Description | Required |
|---|---|
| | |
| | |
| | |

## Work Completed Notes

## Materials Used

| Description | Location | Used |
|---|---|---|
| | | |

**The above works have been supplied and installed to my complete satisfaction.**

**Customer:**

Print Name _____ Signature _____

**The above works have been supplied and installed as per relevant Australian Standards.**

**Technician:**

Print Name _____ Signature _____