**Able Door Services (NSW) Pty Ltd**
ABN 90 097 064 527
507-509 Victoria Street
Wetherill Park NSW 2164

Tel. 02 9757 1877
Fax. 02 9757 1652
www.abledoors.com.au
doorservice@abledoors.com.au

# CUSTOMER JOB NO. 44150

| Site Details | |
|---|---|
| **Name** | UNIT 2/2-10 SEYMOUR STREET |
| **Address** | UNIT 2/2-10 SEYMOUR STREET<br>DRUMMOYNE NSW 2047 |
| **Contact** | DORIS |
| **Telephone** | 0416 443 837 |
| **Mobile** | |
| **Email** | |

| Customer Details | |
|---|---|
| **Name** | SP 50887 C/- FIVE DOCK REALTY |
| **Address** | 92A GREAT NORTH ROAD<br>FIVE DOCK NSW 2046 |
| **Contact** | JOHN LA MELA |
| **Telephone** | 02 9713 2555 |
| **Mobile** | |
| **Email** | info@fivedockrealty.com.au |

## Work Requested

**DOOR SERVICE REQUEST**
**JOB # 44150**

**JOB COMPLETE -**
**TECH -**

CARRY OUT GENERAL SERVICE TO 1 X TILT-A-DOOR
CHECK & TEST FOR CORRECT OPERATION

QUOTE ANY FURTHER WORKS/PARTS IF REQUIRED

****CONTACT DORIS TO ARRANGE A DATE/TIME FOR ATTENDANCE****

## Schedule

| Date Schedule | Date Performed | Scheduled Start | Scheduled Finish | Actual Start | Actual Finish | Total |
|---|---|---|---|---|---|---|
| | | | | | | |
| | | | | | | |
| | | | | | | |

## Work to be Performed

| Description | Required |
|---|---|
| | |
| | |
| | |

## Work Completed Notes

## Materials Used

| Description | Location | Used |
|---|---|---|
| | | |
| | | |

**The above works have been supplied and installed to my complete satisfaction.**

**Customer:**

Print Name _____ Signature _____

**The above works have been supplied and installed as per relevant Australian Standards.**

**Technician:**

Print Name _____ Signature _____