**Able Door Services (NSW) Pty Ltd**
ABN 90 097 064 527
507-509 Victoria Street
Wetherill Park NSW 2164

Tel. 02 9757 1877
Fax. 02 9757 1652
www.abledoors.com.au
doorservice@abledoors.com.au

# CUSTOMER JOB NO. 45931

## Site Details

| | |
|---|---|
| **Name** | ANIMAL CARE FACILITY |
| **Address** | 2 ROSE STREET<br>CAMPBELLTOWN NSW 2560 |
| **Contact** | |
| **Telephone** | |
| **Mobile** | |
| **Email** | |

## Customer Details

| | |
|---|---|
| **Name** | CAMPBELLTOWN CITY COUNCIL |
| **Address** | CIVIC CENTRE 91 QUEEN STREET<br><br><br>CAMPBELLTOWN NSW 2560 |
| **Contact** | GLENN FISHER |
| **Telephone** | 4645 4806 |
| **Mobile** | 0419 467 891 |
| **Email** | glen.fisher@campbelltown.nsw.gov.au |

## Work Requested

**DOOR SERVICE REQUEST**
**JOB # 45931**

**JOB COMPLETE - 15/09/2025**
**TECH - A/DOORS**

**KENNEL D6**
WINDOW SHUTTER - A PIECE HAS DISLODGED FROM THE TOP
SEE ATTACHED PHOTO
INSPECT AND REPAIR AS BEST AS POSSIBLE
QUOTE ANY FURTHER WORKS IF REQUIRED

****ON SITE UNTIL 4PM - CALL WITH AN ETA PRIOR****

## Schedule

| Date Schedule | Date Performed | Scheduled Start | Scheduled Finish | Actual Start | Actual Finish | Total |
|---|---|---|---|---|---|---|
| | | | | | | |
| | | | | | | |
| | | | | | | |

## Work to be Performed

| Description | Required |
|---|---|
| | |
| | |
| | |

## Work Completed Notes

## Materials Used

| Description | Location | Used |
|---|---|---|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

**Able Door Services (NSW) Pty Ltd**
ABN 90 097 064 527
507-509 Victoria Street
Wetherill Park NSW 2164

Tel. 02 9757 1877
Fax. 02 9757 1652
www.abledoors.com.au
doorservice@abledoors.com.au

## CUSTOMER JOB NO. 45931

**The above works have been supplied and installed to my complete satisfaction.**

**Customer:**

Print Name _____ Signature _____

**The above works have been supplied and installed as per relevant Australian Standards.**

**Technician:**

Print Name _____ Signature _____