**Able Door Services (NSW) Pty Ltd**
ABN 90 097 064 527
507-509 Victoria Street
Wetherill Park NSW 2164

Tel. 02 9757 1877
Fax. 02 9757 1652
www.abledoors.com.au
doorservice@abledoors.com.au

# CUSTOMER JOB NO. 50442

| Site Details | |
|---|---|
| **Name** | 10 NASSAU LANE |
| **Address** | 10 NASSAU LANE<br>ERSKINEVILLE NSW 2043 |
| **Contact** | SUSANNA NICKOLAS |
| **Telephone** | 0402 908 217 |
| **Mobile** | |
| **Email** | sknickolas@gmail.com |

| Customer Details | |
|---|---|
| **Name** | NICKOLAS, SUSANNA |
| **Address** | 10 NASSAU LANE<br>ERSKINEVILLE NSW 2043 |
| **Contact** | SUSANNA NICKOLAS |
| **Telephone** | 0402 908 217 |
| **Mobile** | |
| **Email** | sknickolas@gmail.com |

## Work Requested

**DOOR SERVICE REQUEST**
**JOB # 50442**

**JOB COMPLETE -**
**TECH -**

PANEL LIFT WHEEL POSSIBLY OUT OF TRACK
DOOR OUT OF ALIGNMENT
SEE PHOTOS ATTACHED
REPAIR AND TEST FOR CORRECT OPERATION

*****CONTACT SUSANNA TO ARRANGE ACCESS*****

## Schedule

| Date Schedule | Date Performed | Scheduled Start | Scheduled Finish | Actual Start | Actual Finish | Total |
|---|---|---|---|---|---|---|
| | | | | | | |
| | | | | | | |
| | | | | | | |

## Work to be Performed

| Description | Required |
|---|---|
| | |
| | |
| | |

## Work Completed Notes

## Materials Used

| Description | Location | Used |
|---|---|---|
| | | |
| | | |

**The above works have been supplied and installed to my complete satisfaction.**

**Customer:**

Print Name _____ Signature _____

**The above works have been supplied and installed as per relevant Australian Standards.**

**Technician:**

Print Name _____ Signature _____