

Supporting Photos



Basement carpark - fire damage & debris



Basement carpark - fire damage & debris



Basement carpark - fire damage & debris in Unit 7 lock up garage garage space



Basement carpark - fire damage & debris in Unit 7 lock up garage garage space



Basement carpark - fire damage & debris



Basement carpark - fire damage & debris



overview carpark area and existing services



overview carpark area and existing services



overview carpark area and existing services



disconnected/made safe services in unit 7 garage



cause of fire advised as overloaded power



fire damaged aerial water, drainage and gas services located in Unit 7 garages



fire damaged aerial water, drainage and gas services located in Unit 7 garages



fire damaged aerial water, drainage and gas services located in Unit 7 garages



fire damaged aerial water, drainage and gas services located in Unit 7 garages



Tilt lift door typical - 2100 x 2700 wide



Garage tilt-a-door typical



Tilt lift door typical - 2100 x 2700 wide



Tilt lift door typical - 2100 x 2700 wide



aerial drainage adjacent unit 10 garage and away from unit 7 garage fire



fire damaged CCTV unit mounted on concrete beam adjacent unit 10 garage



overview gas meters adjacent to unit 7 garages



overview - unit 8 garages opposite unit 7 garages



fire damaged aerial water, drainage and gas services located in Unit 7 garages



fire damaged aerial water, drainage and gas services located in Unit 7 garages