JOHNS LYNG NSW

PHOTO SCHEDULE JNEX42451


SITE ADDRESS 311 High Street, Penrith, NSW 2750
CONTACT NAME Lindy Johnson
CLIENT REFERENCE 6181618

PHOTOGRAPHS

CF262382 Supporting Images

Site Photos

Site Photos



Carpark



Smoke stained walls




Fire Exit Passage



Carpark Area Overview



Fire Exit Passage




Carpark - Fire damaged ceiling mesh



Carpark - Fire damaged mesh



Carpark - Fire damaged mesh



Carpark - Fire damaged mesh



Fire Exit Passage - Fire damage to brickwork and ceiling



Area Overview



Fire damaged chain fence



Fire damaged electricials



Fire Damaged Ceiling Joist



Fire Exit Passage - Soot stained walls



Fire damaged electricals



Area Overview



Fire Exit Passage - Soot staining



Fire damaged electricals



Fire damaged chain fence



Fire Exit Passage - Soot staining



Fire Exit Passage - Soot staining



Stained brickwork