JOHNS LYNG - ALEXANDRIA - KTA040424P

Job #28366

Status: Completed

Client:
JOHNS LYNG
11 Birmingham Street
Alexandria
2015
New South Wales

Date	Description	Quantity
2025/03/25 11:52	ROLLER DOOR ATTEND SITE TO FIND MOTOR STRUGGLING TO LIFT DOOR DOOR SEEMS TO BE OKAY JUST NEED TO REFIX GUIDES WITH BETTER FIXINGS DUR TO BEING BLOWN IN AFTER A STORM ROLLER SHUTTER THE GUIDES ARE LOOSE ON THE BRICKWORK. NEED TO RE FIX WITH BETTER FIXINGS	1.00

Attachment photo.jpg

Description: roller door photos



Attachment photo.jpg

Description: photos of existing motor



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: roller shutter photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos



Attachment photo.jpg

Description: photos

