



Any Door & Gates Pty Ltd
 PO BOX 264
 Pendle Hill NSW 2145
 Tel: 1300 808 430
 Fax: 02 9863 7727
 sales@anydoor.com.au

ABN: 26 137 909 758

Tax Invoice No: 1118950

Issue Date: 5/4/2023

Due Date: 5/4/2023

Invoice To

All Doors (NSW) Pty Ltd
 Dom /Jayme

NSW

Reference

Cust On:

Job No: 21624

Rivers - 17 Marco Avenue

Description	Revesby	Unit Charge	Total
Rivers - 17 Marco Avenue Revesby Please attend site doors not opening			
Detail of Work Completed			
1	Attended site inspected auto door found door is non responsive, have reset door controller door is now working, this is an ongoing issue as auto door operator is extremely old and has electrical faults. This issue will more than likely reoccur again. Left door working	\$295.00	\$295.00
			\$295.00

Please send Remittance Advise via email to accounts@anydoor.com.au

Terms	Direct Debit	Cheque	Credit Card	Subtotal:	\$295.00
Full payment within	Commonwealth Bank	Cheques Payable to	Call 1300 808 430	GST:	\$29.50
	BSB: 062 224	Any Door & Gates Pty Ltd		Total:	\$324.50
	Account: 102 05184	PO BOX 264	1.5% surcharge VISA +		
		Pendle Hill NSW 2145	MasterCard + Bankcard		



This payment claim is made under the Building and Construction Industry Security of Payment Act 1999 (NSW) or the Building and Concstruction Industry Security of payment Act 2002 (VIC), 2004 (QLD), 2009 (ACT) which ever applies. All Materials Remain the Property of Anydoor & Gates until Full Payment has been Received.



Any Door & Gates Pty Ltd
 PO BOX 264
 Pendle Hill NSW 2145
 Tel: 1300 808 430
 Fax: 02 9863 7727
 sales@anydoor.com.au

ABN:26 137 909 758

Task Sheet

Issue Date: 30/3/2023

Details

Task: Repairs Rivers - 17 Marco Avenue
 Revesby
 Client: All Doors (NSW) Pty Ltd
 Requested: 30/3/2023 12:10PM
 Client Contact:

Reference

21624
 Job No:
 Cust On:
 Site: Rivers - 17 Marco Avenue
 Revesby

Description:

Please attend site doors not opening

REMARKS

Attended site inspected auto door found door is non responsive, have reset door controller door is now working, this is an ongoing issue as auto door operator is extremely old and has electrical faults. This issue will more than likely reoccur again. Left door working

Checklist	Completed	Y	N	N/A	Comments	GPS
Complainace Forms	30/3/2023 @ 3:26PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Arrived on Site	30/3/2023 @ 3:26PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Items Checked Item OK	30/3/2023 @ 3:34PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Items Adjusted Item OK	30/3/2023 @ 3:34PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Items Safe for use	30/3/2023 @ 3:34PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Site left clean & tidy	30/3/2023 @ 3:34PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Captured Signatures	30/3/2023 @ 3:34PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		

Completed By:

Completed: 30/3/2023 @ 3:34PM

Signatures:

Ranjeetha bhangadia 30/3/2023

Mohammad 30/3/2023