Work Order Number: 0004033

Date: 29 Sep 2025

Combined Commercial Pty Ltd

Po Box 201

Narellan NSW 2567

AUSTRALIA

ABN 83 138 431 179

To Supplier:

All Doors (NSW) Pty Ltd

PO Box 132

Leppington

NSW 2179

AUSTRALIA

Email to:

sales@alldoorsnsw.com.au

Location Details

Property Manager Name:	Brandie Hodge
Property Manager Email:	brandie@combinedcommercial.com.au
Property Manager Phone:	0246479455
Property Name:	2-10 Dunn Road
Property Address:	2-10 Dunn Road SMEATON GRANGE NSW 2567 AUSTRALIA
Tenant Name:	Andrew KANATLI
Tenant Phone:	
Tenant Mobile:	61 488587040
Tenant Email:	andrew@kaplanhomes.com.au
Area Name:	Unit 1, 2-10 Dunn
Nature of work:	
Priority:	High

Work Description:

Hi there,
Our tenant at the above site advised that the roller door is playing up and stopping about 2ft from the bottom every 5-6 attempts. The track sounds good and greased, but the motor and cogs look very dusty – see attached photo.

The door was only serviced in July this year. Please contact Anthony 0466 444 075 for access.
Could you please investigate this further.
Thanks
Brandie

Additional Information:

Images:

Invoicing to:

Please ensure Work Request number is noted on invoicing

CNC (NSW) Pty Ltd

Care of:

Combined Commercial Pty Ltd

Po Box 201

Narellan NSW 2567

AUSTRALIA

Email invoices to: admin@combinedcommercial.com.au

Disclaimer: