



Any Door & Gates Pty Ltd
 PO BOX 264
 Pendle Hill NSW 2145
 Tel: 1300 808 430
 Fax: 02 9863 7727
 sales@anydoor.com.au

ABN: 26 137 909 758

Tax Invoice No: 1118552

Issue Date: 20/1/2023

Due Date: 20/1/2023

Invoice To

All Doors (NSW) Pty Ltd
 Dom /Jayme

NSW

Reference

Cust On: jayme

Job No: 20846

ground floor
 8 cross street

Description	Unit Charge	Total
-------------	-------------	-------

ground floor brookvale

[Ground Floor , Ground Floor, 8 Cross Street Brookvale](#)

[Please undertake a service of the rollers and operational mechanism of the front Tormax Automatic Glass Door \(model GEP\). Tenant has reported periodic issue with closing the door. Don't believe it is a motor issue.](#)

[GRAHAM - 61 477754085](#)

Detail of Work Completed

1	Attended site found no matter how many times I adjust drive belt it goes back to the edge highlighting the gearing drive is worn and needs to be replaced the drive wheels on the carriages are rusted also wear and tear Recommend to complete replace operator spoke to graham All good submit quote	\$295.00	\$295.00
			\$295.00

Please send Remittance Advise via email to accounts@anydoor.com.au

Terms	Direct Debit	Cheque	Credit Card	Subtotal:	\$295.00
Full payment within	Commonwealth Bank	Cheques Payable to	Call 1300 808 430	GST:	\$29.50
	BSB: 062 224	Any Door & Gates Pty Ltd		Total:	\$324.50
	Account: 102 05184	PO BOX 264	1.5% surcharge VISA +		
		Pendle Hill NSW 2145	MasterCard + Bankcard		



This payment claim is made under the Building and Construction Industry Security of Payment Act 1999 (NSW) or the Building and Concstruction Industry Security of payment Act 2002 (VIC), 2004 (QLD), 2009 (ACT) which ever applies. All Materials Remain the Property of Anydoor & Gates until Full Payment has been Received.



Any Door & Gates Pty Ltd
 PO BOX 264
 Pendle Hill NSW 2145
 Tel: 1300 808 430
 Fax: 02 9863 7727
 sales@anydoor.com.au

ABN:26 137 909 758

Task Sheet

Issue Date: 23/11/2022

Details

Task: Repairs ground floor brookvale
 Client: All Doors (NSW) Pty Ltd
 Requested: 23/11/2022 1:43PM
 Client Contact:

Reference

Job No: 20846
 Cust On: jayme
 Site: ground floor
 brookvale

Description:

[Ground Floor , Ground Floor, 8 Cross Street Brookvale](#)

Please undertake a service of the rollers and operational mechanism of the front Tormax Automatic Glass Door (model GEP). Tenant has reported periodic issue with closing the door. Don't believe it is a motor issue.

REMARKS - [GRAHAM - 61 477754085](#)

Attended site found no matter how many times I adjust drive belt it goes back to the edge highlighting the gearing drive is worn and needs to be replaced the drive wheels on the carriages are rusted also wear and tear Recommend to complete replace operator spoke to graham All good submit quote

Checklist	Completed	Y	N	N/A	Comments	GPS
Complaince Forms	23/11/2022 @ 3:04PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Map Link
Arrived on Site	23/11/2022 @ 3:04PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Items Checked Item OK	23/11/2022 @ 3:47PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Items Adjusted Item OK	23/11/2022 @ 3:47PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Items Safe for use	23/11/2022 @ 3:47PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Site left clean & tidy	23/11/2022 @ 3:47PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Captured Signatures	23/11/2022 @ 3:47PM	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		Map Link

Completed By:

Completed: 23/11/2022 @ 3:47PM

Signatures:

Roman 23/11/2022

Joe 23/11/2022