# Purchase Order / ID #190478

**Issue Date: 09.08.2023** **Time Out Date:** **Due Date Completion: 14.08.2023**

**This Request will timeout if you do not select a button to confirm your status**

CLICK HERE TO **SCHEDULE INSPECTION**
This will confirm the inspection date / time with ALL site contacts

CLICK HERE TO **SCHEDULE WORK**
This will confirm the job date / time with all site contacts

CLICK HERE TO **ADD INVOICE**
Invoices will be sent to the strata manager and owners corporation for approval

CLICK HERE TO INDICATE YOU'RE **AWAITING MATERIALS**

CLICK HERE TO INDICATE YOU'RE **AWAITING SITE CONTACT**

CLICK HERE TO **MESSAGE STRATA MANAGER**

CLICK HERE TO **DECLINE JOB**

## Supplier

**Name:** All Doors (NSW) Pty Ltd
**Business Number:** 96128338643
**Phone:** 0417528785
**Email:** sales@alldoorsnsw.com.au

## Strata Management Company

Independent Unit Management
Business Number
Postal Address:
Phone:

## Job Address

**Plan Number:** 32950
**Building Address:** 398 MARION STREET
**Suburb:** BANKSTOWN
**Postcode:** 2200

## Invoice Details

32950: 398 MARION STREET, BANKSTOWN, 2200, NSW
c/o Independent Unit Management
Phone:
Email:

## Suggested Time for Access

## Shared / Important Building Documents

## Strata Manager(s)

**Name:** Mary Gahdmar
**Phone:** 81993664
**Email:** mgahdmar@ium.com.au

**Name:** Angelica Macris
**Phone:** 98227800
**Email:** amacris@ium.com.au

## Access Contact(s)

**Name:** Chris - Guest
**Lot #:** / **Unit #:**
**Phone:** 0438700797
**Email:**

## Job Details

**Job Title:** U15 - Roller Shutter Damaged
**Job ID:** 190478
**Job Description:** Please attend to the damaged roller shutter that has been impacted from the exterior as seen in the photos attached. Agent advised "Recently the roller shutters have become more difficult to operate due to the damage. They are also concerned about the security of the warehouse given that the external dent has created a gap at the side of the rail as pictured." Thank you.
(VIEW ATTACHMENTS)