Work Order / ID #332987

Issue Date: 07.06.2024 **Time Out Date:** **Due Date Completion: 21.06.2024**

CLICK HERE TO **SCHEDULE INSPECTION**
This will confirm the inspection date / time with ALL site contacts

CLICK HERE TO **SCHEDULE WORK**
This will confirm the job date / time with all site contacts

CLICK HERE TO **ADD INVOICE**
Invoices will be sent to the strata manager and owners corporation for approval

CLICK HERE TO INDICATE YOU'RE **AWAITING MATERIALS**

CLICK HERE TO INDICATE YOU'RE **AWAITING SITE CONTACT**

CLICK HERE TO **MESSAGE STRATA MANAGER**

CLICK HERE TO **DECLINE JOB**

Supplier

Name: All Doors (NSW)
Business Number: 96128338643
Phone: Jayme - 0417975669
Email: sales@alldoorsnsw.com.au

Strata Management Company

Independent Unit Management
Business Number
Postal Address:
Phone:

Job Address

Plan Number: 32950
Building Address: 398 MARION STREET
Suburb: BANKSTOWN
Postcode: 2200

Invoice Details

32950: 398 MARION STREET, BANKSTOWN, 2200, NSW
c/o Independent Unit Management
Phone:
Email:

Suggested Time for Access

Shared / Important Building Documents

Strata Manager(s)

Name: Mary Gahdmar
Phone: 81993664
Email: mgahdmar@ium.com.au

Name: Angelica Macris
Phone: 98227800
Email: amacris@ium.com.au

Access Contact(s)

Name: Mohammed El Chami Extreme Metal Works - Tenant
Lot #: 16 / **Unit #:** 16
Phone: 0426 426 364
Email: moe.e.c@hotmail.com

Job Details

Job Title: FU16 - roller shutter
Job ID: 332987
Job Description: Roller shutter has been gradually becoming more difficult to operate. Please attend and investigate/repair Thank you.

Please ensure contractors comply with the Asbestos Survey and Management Plan on site if applicable.