

BME Group
Shop 107/8 Nuvolari Place
Wentworth Point, New South Wales
2127

WORK ORDER #: 156

April 25, 2025

Authorized By	Issued To
BME Group Shop 107/8 Nuvolari Place Wentworth Point, New South Wales 2127	**All Doors NSW** , New York 0417 975 669 **The vendor has no contacts**

Job Location

The Surry
3 Butt Street
, New South Wales 2010
Bldg Mgmt

Lea-Anne Swan
bm1@bmegroup.com.au
0414 711 030

Job Details

Work to be Done:
Building Management has been advised that the car park roller door is stuck in the open position and requires attention.

Access Instructions:
Please notify Building Management when on the site

Contractor/Vendor Completion Details

Contractor/Vendor Name:

Date/Time on Site:
Arrived on Site:
Hours Worked:

Warranty for Labor:

Warranty for Parts:

Further Work Required:

Action take:

Charges:

Signature:

Service and Labor	Hours	Rate	Line Total

Subtotal	
Tax	
Total	

Parts and material	Quantity	Unit Price	Line Total

Sub Total	
Tax	
Shipping	
Other	
Total	