

Purchase Order / ID #124607

Issue Date: 31.01.2023

Time Out Date: 02.02.2023

Due Date Completion: 31.01.2023

This Request will timeout if you do not select a button to confirm your status

CLICK HERE TO
SCHEDULE INSPECTION

This will confirm the inspection date / time with ALL site contacts

CLICK HERE TO
SCHEDULE WORK

This will confirm the job date / time with all site contacts

CLICK HERE TO
ADD INVOICE

Invoices will be sent to the strata manager and owners corporation for approval

CLICK HERE TO INDICATE YOU'RE
AWAITING MATERIALS

CLICK HERE TO INDICATE YOU'RE
AWAITING SITE CONTACT

CLICK HERE TO
MESSAGE STRATA MANAGER

CLICK HERE TO
DECLINE JOB

Supplier

Name: All Doors (NSW) Pty Ltd
Business Number: 96128338643
Phone: 0417528785
Email: sales@alldoorsnsw.com.au

Strata Management Company

Westside Strata Management
Business Number
Postal Address:
Phone:

Job Address

Plan Number: 74146
Building Address: 58 Bathurst Street
Suburb: LIVERPOOL
Postcode: 2170

Invoice Details

74146: 58 Bathurst Street, LIVERPOOL, 2170, NSW
c/o Westside Strata Management
Phone:
Email:

Suggested Time for Access

Shared / Important Building Documents

Strata Manager(s)

Name: Rebekah Birchall
Phone: 0432 164 174
Email: rebekah@westside.net.au

Access Contact(s)

Name: Ramzi Haidar - Owner Occupier, Committee Member (Committee Member)
Lot #: 4 and 4 / **Unit #:** 4
Phone: 0414 598 334
Email: ramzihdr@gmail.com

Job Details

Job Title: Issue with Garage Door
Job ID: 124607

Job Description: Hi All Doors, there is an issue with the garage door which had constantly been going up and down. The committee looked into this and it appears that this is due to the garage door reflector being incorrectly angled downwards (photo attached for your reference) The center of the round reflector is around 40mm from the center of where the infra-red light beam would strike.

Please arrange to attend to this

[\(VIEW ATTACHMENTS\)](#)