Quote Request / ID #345896

Issue Date: 02.07.2024 **Time Out Date:** **Due Date Completion: 03.08.2024**

CLICK HERE TO
SCHEDULE INSPECTION
This will confirm the inspection date / time with ALL site contacts

CLICK HERE TO
ATTACH QUOTE
Quotes will be share with the strata manager / owners corporation

CLICK HERE TO
MESSAGE STRATA MANAGER

CLICK HERE TO
DECLINE JOB

Supplier

Name: All Doors (NSW)
Business Number: 96128338643
Phone: Jayme - 0417975669
Email: sales@alldoorsnsw.com.au

Strata Management Company

Independent Unit Management
Business Number
Postal Address:
Phone:

Job Address

Plan Number: 18053
Building Address: 31-33 Belmont Road
Suburb: GLENFIELD
Postcode: 2167

Invoice Details

18053: 31-33 Belmont Road, GLENFIELD, 2167, NSW
c/o Independent Unit Management
Phone:
Email:

Suggested Time for Access

Shared / Important Building Documents

Strata Manager(s)

Name: Philomena Romanous
Phone:
Email: promanous@ium.com.au

Name: Jason Vyas
Phone:
Email: jvyas@ium.com.au

Job Details

Job Title: V11 roller door not working
Job ID: 345896
Job Description: could you please supply a quote to replace or repair the roller door to unit 11 a the owner is finding it very hard to open and close Villa11 Mayan 0470 067 522

Please ensure contractors comply with the Asbestos Survey and Management Plan on site if applicable.